


LEGENDE :

- BORNE DE RACCORDEMENT
- SHUNT VC
- CABLAGES USINE
- CABLAGES INSTALLATEUR

ALIMENTATION SECTEUR 400Vca+N+T 50Hz



BORNIER X DE RACCORDEMENT

PRESSOSTAT SECURITE	CONTACT	Noir	1			
PRESSOSTAT SECURITE	CONTACT	Noir	2			
PRESSOSTAT BP	CONTACT	Noir	3			
PRESSOSTAT BP	CONTACT	Noir	4			
ALIM. 230VCA	PHASE 230V	Noir	5			
ALIM. 230VCA	NEUTRE 230V	Bleu	N	N		
RESISTANCES CARTER	PHASE 230V	Noir	6			
RESISTANCES CARTER	NEUTRE 230V	Bleu	N	N		
PRESSOSTAT HP VC	CONTACT	Noir	7			
PRESSOSTAT HP VC	CONTACT	Noir	8			
			9			
			10			

KRIWAN CONTACT

SHUNT 7 & 10 = VC CLASSIQUE

SHUNT 9 & 10 = VC PAR HP